



WICKMAN

MACHINE TROUBLESHOOTING.

Wickman Coventry Limited.

Unit A, Three Spires industrial Estate, Ibstock Road, Coventry CV6 6JR

Telephone +44 (0) 1203 644511 Spares +44 (0) 1203 644055 Facsimile +44 (0) 1203 644130/644069

FRESH EYES

When anyone has fought trouble about so long, he gets to the point where he couldn't see the solution if it were written on the wall. The only cure is to walk away, do something else long enough to regain perspective, or get someone else to take a look.

In either case, come back to the job as if it had never been seen before. Take nothing for granted. Run a group of consecutive parts and check them against the print, writing down the findings. Then, define in writing exactly what is wrong. Just this simple re-evaluation and restatement of the problem often points to an answer which has been overlooked. If so, it probably turns out to be some mistake or misunderstanding which needed only fresh eyes to be seen. In any event, we need written record of how the job behaved for comparison with results after changes have been made.

The problem in every case will fall into one of four categories:

1. TOOL LIFE
2. VARIATION
3. CONCENTRICITY
4. SURFACE FINISH

Of course, more than one trouble may be present, but the cause will be one or more of these seven variables:

1. SPINDLE SPEED
2. FEED
3. COOLANT
4. TOOLING
5. MACHINE
6. PART
7. HUMAN

In Table VIII-1 the four troubles are listed from left to right in the order in which they are most likely to occur. Beneath each trouble, in declining order of probability, are the seven possible causes. This table is the result of the writer's findings in more than 10 years of screw machine troubleshooting experience. It is suggested that once the trouble is known, the variables be examined in the order shown. Note the priority of variables differs from one problem to another.

TABLE VIII-1

Tool Life	Variation	Concentricity	Surface Finish
Spindle Speed Feed Coolant Tooling Machine Part Human	Machine Feed Tooling Part Spindle Speed Coolant Human	Machine Tooling Feed Part Spindle Speed Coolant Human	Machine Feed Spindle Speed Tooling Coolant Part Human

ARE YOU SURE?

Before we move into systematic analysis of cause, however, we need to know what conditions exist on the machine. By the time troubleshooting begins in earnest, one or several persons most likely have made a stab at fixing the condition, and in all probability no one is absolutely sure what's been done. So, immediately after pinpointing the problem, double check all seven variables, taking no one's word (least of all your own) for anything.

Determine personally, and note in writing that:

1. Spindle speed is in fact what it is thought to be, and that s.f.m. is reasonable for the material and the operation.
2. Feed is as called for, and motion is smooth and uniform throughout the stroke.
3. Coolant appears clean, is being applied properly, and is of a type recommended for the work.
4. The machine has no apparent defects needing attention.
5. Proper tool grades are being used, and tools have been properly ground to specified geometries.
6. The part print is fully understood, and its tolerances are within the capability of the equipment as set up.
7. The operator has a positive attitude, and adequate skill for the job.

Like the first step, this is a fact-gathering function, but here again things which have been overlooked or taken for granted may point to the answer. Although in this article we assume the task is to solve trouble without changing work material, we should during this initial study make sure the specified grade is in fact being used.

Note that to this point the method ignores what's-been-done, concentrating instead on what's-wrong, and where-we-are. This is important because if the job has been cobbled.

juggled and fooled-with, as is probably the case, we need to have written record of prior conditions and effect in order to judge results as changes are made. It is entirely possible that as one variable is brought into line error will show up elsewhere. Don't be discouraged by that. It is an indication counterbalancing is being eliminated.

CLUES

The effect of conditions always shows up on the three elements of a metal cutting operation: The part, the chip and the tool. An advantage of experience is that with it one recognizes the results which should be obtained with a given material cut at given s.f.m. and feed with a given shape and type of tool with a given coolant. That's why old-time troubleshooters look in the chip pan for answers to problems on a machine. If you can make good chips, chances are you can make acceptable parts, always assuming the machine is capable of holding the necessary tolerances.

Each type of steel has a characteristic chip. The free-machining grades should produce short, bright broken ones. Ductile grades yield long, stringy chips. The higher alloy, and work-hardening materials, such as 1137, 1141, and 1144, may give off one or the other of the above kinds of chips, but the difference is that there may be scabby adhesions on the cut side. All of this should be true if the job is tooled correctly and running at reasonable rate. The old-timer's look at the chips is just one form of analysis by exception; he's looking for conditions which do not fit the pattern.

But in our analysis we shall look at the other two elements of the operation as well: The tool and the workpiece. On the tool we check for discoloration, cratering, built-up edge (BUE) and point-of-wear. We look at the workpiece's cut surface under a glass to determine if the tool rubbed, if work-hardened scabs are present, or if the chip came away cleanly. In this study we're concerned primarily with BUE.

BUE

It should be kept in mind that a BUE is work metal, welded to the tool by heat, and/or pressure and has the same work hardening characteristics as the metal being cut. One of the factors which make leaded and resulfurized low carbon steels "free-machining" is that these additives reduce welding. Hence, in free-machining grades little if any BUE should be found. Tools used on those grades generally wear by rounding off. If craters are found, they're the result of hot chips rubbing across the face of the tool. This hot-rub effect can be seen when the tools are examined under magnification.

In contrast the high manganese and high carbon grades have excellent work hardening qualities, and since these are generally cut at lower speeds (hence lower tool temperature) BUE's tend to form. This is not always bad, because when we have a moderately sized BUE which stays on tool point it may actually prolong the life of the edge.

What we don't want, however, is a BUE which builds and breaks away carrying hardened bits of metal across the top rake or between the tool and the part. If this is occurring, the tool's crater will have a pitted appearance, since a bit of the tool is torn off each time the BUE is lost.

Such a condition will yield sporadic change in work finish and short tool life. It is an indication a different coolant, and possibly changed tool geometries, should be tried. Coolants with active sulfur or chlorine give the operation the anti-weld features not had in the material. Lapped edges, and surface treated tools will also help.

In carbides, BUE is most likely to occur at too-slow s.f.m. The solution is obvious, though not always easy to obtain when other tools limit the speed range. A tip here is when s.f.m. cannot be increased, use a mineral base coolant instead of a water soluble.

With that background, let us consider what is involved in curing trouble in each of the four conditions shown in Table VIII-1, beginning with Tool Life.

TOOL LIFE TROUBLE

"Spindle Speed" is listed as the most likely cause, since speed creates heat, and heat is the most destructive force acting on tools. Indications speed is too high for conditions are when corners of forms, turning tools or cutoffs burn, or when the peripheries of drills, taps or reamers discolor.


In short, the effect is seen where s.f.m. is greatest, or where the tool has least mass, hence least heat-carrying ability. If speed is too slow, unstable BUE's will be seen and wear will show up either as a rubbed condition on tool flanks, or cratering. Note that wear can result from too-slow speed as easily as from excessive speed.

Next is "Feed." If drills split down the middle, or edges chip without discoloring, or large unstable BUE's are seen, feed per revolution should be lowered. An exception to this is when a work hardening material is being machined and the equipment is somewhat loose. In this case, feed should be increased to keep the tool from rubbing and work hardening the surface. The tool must not rub in work hardening grades. Keep it cutting by whatever means is required.

Then we check on "Coolant." A large BUE indicates need for change to a fluid with greater anti-weld properties. If flank wear is seen, the coolant may be overly fortified. The answer: Switch to a thinner fluid with greater oiling action.

Let's pause here to consider what the coolant does and how it should be applied. Coolant (1) carries off heat from the tools and the part, (2) provides an oiling action to the cut and at times puts an anti-weld barrier between tool and material, and (3) flushes away chips. As shown in Figure VIII-2, these actions are enhanced by placement of the oil lines. Quite frequently an extra line will reduce BUE which is causing a tool to chatter. This is particularly helpful in wide forming operations from the cross slide.

FIG. VIII-2



When drilling, aim two lines up the hole, and another over the outside to carry off heat. The thinner the part's wall, the more important the outside line will be, and in deep, thin-wall work where there is little chance of getting much fluid to the drill point, copious amounts of water solubles flowed onto the part's O.D. often are helpful.

Next we investigate "Tooling." Here we shall assume the initial check on variable showed a proper grade of tool is being used. Cratering is most apt to be seen when cutting soft gummy materials, or high strength grades, for the reason mentioned earlier. In either case, smoother grinds and higher rake angles reduce cratering to manageable limits.

If heat craters are seen, it may be worthwhile to consider a shift to T-5 or T-15 H.S.S. which has greater hot hardness and abrasion resistance. In free-machining steels, little or no BUE should be evident if rake is proper for conditions. Remember, we don't want to eliminate BUE altogether, since it protects the cutting edge, but we do want it to be small and stable.

At times BUE's form and wipe off at the end of the cut. By using a 10X glass or better, and seeing how far back the crater extends, you can make a good guess at how much buildup is taking place.

A certain amount of flank wear is normal. Excessive wear on flanks is usually caused by too-little clearance. Increase clearance. If the condition persists, consider a switch to a tool having higher vanadium. When sides of form tools wear excessively, try to eliminate sharp corners. A $1/32$ by 45 degree break will strengthen the edge of forms used on work hardening steels; in others, a small radius may work best, and this, of course, applies to all tools where it can be used.

In evaluating tools for sources of trouble, one must be careful to differentiate between actual wear and breakdown of the edge due to fatigue. The latter is microscopic chipping which can sometimes be noted under magnification. The solution is to first strengthen the edge by reducing rake and clearance. If that doesn't work, switch to a less brittle grade of tool.

Hard-to-cut steels require greater side clearances since they tend to spring back behind the edge. The tipoff on this is when sides of cleared tools gall or bug.

A few miscellaneous tips: Try not to follow any cut with another tool of identical shape, especially on work hardening materials. Make absolutely certain tools are not burned in grinding. Tool life often can be doubled by polishing and honing all edges. A high shine on the part generally indicates tools are rubbing, and the most frequent cause is a cam with too much dwell at the top of the rise. Worn cams and work hardening steels do not go together. Also make sure cross slide stops are not set overtight, since this can cause tool dwell also. Assuming the tool and the part are adequately supported, the most frequent causes of chatter are too much clearance or too great radius on the tool's edge.

The next variable to be studied is "Machine." Note it ranks fifth as a cause of poor tool life, but first in the three other types of trouble. The reason is that the machine contributes here by default failure to provide sufficient rigidity or smoothness of motion which allows tools to rub, or chatter. This will be noted most in brittle tools, such as carbide or ceramics. The effect of worn cams on work hardening steels has been mentioned; loose pins, linkages, slides or spindles will give similar result. If possible, snug up the machine; if not, increase feed and lower speed to keep the tool constantly under pressure.

Let us now consider "Part" as a factor in tool life. The shape of the workpiece, and its tolerances, dictate the type of tools required. If trouble exists, check with Engineering to find out if slight angles are allowable on deeply cut straight sides, or if sharp corners are necessary.

Necks less than three threads wide almost always will reduce chaser or tap life by making shorter lead chamfers necessary. My rule for side cutting angles on forms is: In free-machining steels, 1/2 to three degrees positive; in ductile steels, five degrees, and in work hardening grades, eight to 10 degrees. It may not be possible to change part shape, but it's an area worth exploring.

Finally, we look at the "Human" factor, which ranks last in all four types of trouble. The reason is that if the man on the job is grossly unable or unwilling to handle the work, this should have shown up in the preliminary check on the seven possible variables. Nevertheless, spending time with the operator and explaining the reasons why the job must be done a certain way may give him a better grasp of the function, let him use his experience to further the desired result, and will give him a more positive attitude toward the job.

Somewhere within the definition of the problem, the preliminary doublecheck on conditions, or the more detailed analysis of the seven causes, the answer to tool life problems will be found.

VARIATION

As shown in Table VIII-1, the causes of dimension-to-dimension, or piece-to-piece changes in product are, in order of probability, Machine, Feed, Tooling, Part, Spindle Speed, Coolant, and Human.

"Machine" is the most likely troublemaker because, quite obviously, if tools were carried a like distance on each stroke and forced into the cut with equal pressure, parts should be alike. Something within the machine probably is allowing this sameness of motion to be disturbed. On a multiple-spindle automatic, variations in length, part-to-part, indicate end play in spindles, or erratic stock feeding; possibly "bounce" off the stock stop. On single-spindle models, length variation can also be caused by the foregoing, along with worn lead cam rollers and pins.

On either type, part-to-part changes in formed dimensions generally indicate bad spindles, faulty cross slide systems, or improperly set stop screws. This type of trouble is spotted on multiples by recording the dimensions of the parts from each spindle. Of course, if the problem is that simple, it should have been noted in the initial problem-finding stage. Even so, a graphed picture of a larger group of parts is a help, and may show relationships between dimensional variances which point to the cause in the most sticky types of trouble, the cases where a part is out of tolerance "just once in a while."

When large diameter stock is run in an older machine, the weight of 12-foot bars may cause deflection. To determine if this is the cause, cut bars in half or check the job when bars have been partially used up.

Anything which encourages vibration will affect tolerances. Snug up slide gibs, replace rollers, check end play, stop screw tensions, and make sure tools are solidly mounted and cams are tight.

The next most likely cause of variation is "Feed." Its chief effect is to increase endwise and sidewise pressures, hence if the machine is known to be somewhat sloppy, lower feed may give best results. Remember, though, as pointed out previously, that with work hardening steels, tools must have sufficient feed so they do not rub. We can also decrease feed per revolution by running at higher r.p.m. In other words, the pushing effect of feed can be minimized without lengthening cycle time in many cases. As a general policy, however, very close dimensional limits usually require feeds to be rather light for finishing cuts.

Next we turn to the "Tooling" variable. This is a factor in dimensional variation whenever tools are dull, chipped or incorrectly set or cleared. The effect is much the same as too-heavy feed: Cutting pressures are exerted which may be greater than the machine can take without deflecting. As was mentioned, watch for BUE's which build up and wipe off. Also make sure tools are *not* burned in grinding, since burned tools dull faster.

Tools which are grouped closely together are a likely source of the problem when variation occurs "just once in awhile." If there is not enough room for chips to fall free, they may pack and hold back a slide, or prevent oil from reaching tool points. The cure is to rearrange tools, or to give them chip-breakers so packing does not occur.

In considering "Part" as a variable, it must be recognized that if tolerances were wide open there would be no variation problem. This is just another way of saying the closer the limits the more chances of producing parts which fall outside them. As previously discussed, work with Engineering to get too-tight limits opened up, if possible, or tricky configurations changed to less troublesome ones.

While "Spindle Speed" ranked first as a cause of poor tool life, it stands fifth as a probable source of product variation. If the part is long, and must extend a great distance from the collet, lower speeds may cut down vibration and whip. It is more likely, though, that if this condition exists to a hindering degree, the part should be given extra outboard support.

"Coolant" comes sixth. By rearranging lines or adding high velocity lines aimed near the point of cutting, but not on it, it may be possible to flush away chips which would otherwise pack and cause variation. Of course, by keeping tools sharp longer a good coolant helps produce more uniform work.

Finally, the "Human" factor. No one is in better position to spot trouble in its early stages than the man at the machine. He should be instructed to report abnormal conditions, set tools and slides properly, and in general know if his equipment "acts right."

CONCENTRICITY

For trouble of this sort we investigate variables in the following order: Machine, Tooling, Feed, Part, Spindle Speed, Coolant and Human. The first four are by far the most important; the remaining three incidental.

"Machine" comes first because concentricity or rather, the lack of it almost always involves misalignment of tools to workpieces. You simply cannot drill, ream or bore a hole concentric to an outside diameter if the spindle is sloppy. On multiples, check for spindle carrier lockup.

In every case go over the slides, the spindle, and every element which affects tool-work rotational relationship. When a machine which has been on one job a long time is changed over to one of different length, a sudden show-up of eccentric conditions may be due to the slide having worn in one spot.

There is, of course, the possibility that hole eccentricity originates in a wobbling drill. However, if the problem is greater, check the machine with a dial indicator.

"Tooling" as a cause of eccentric conditions is most apt to show up in the hole. Here it should be said that while the initial definition of the problem should have made clear which dimensions were out of tolerance, it is not always easy to determine whether an O.D. is eccentric to a hole or the hole is eccentric to the outside of the part.

As an example, consider a simple collar, formed all over to one size, and having a straight through hole. Assuming both I.D. and O.D. are found to be round, which is eccentric? Nine times out of 10 it will be the hole, and the tipoff is that O.D. chamfers are true, while I.D. chamfers are not. As good a way as any to tell what is wrong is to shut off the coolant and watch a part finished but not yet cut from the bar as it rotates. In this way hole wobble or O.D. runout can be seen at once. The best way to make this decision is, of course, to use the indicator on the part before it is parted from the bar. If a hole is off center, check the drill point first. It may be chipped, ground off center, or improperly thinned. Regardless of what anyone says, drills used in steel must be thinned to about 1/10th of the drill diameter for drills one inch or larger, 1/15th for 1/2-inch drills, and 1/20th for 1/8-inch drills.

Then there's the matter of lip clearance. In harder steels, clear about seven degrees; in free-machining grades, try 10 to 12 degree clearances. In harder steels, make the included angle of the point blunter. The drill should be choked as short as possible to avoid runout. Watch, too, for small side tools, such as knee turners, facers or hole chamferers which may be pushing a drill off center, or allowing chips to pack between the two. Many times it will be found that side forming, knurling or thread rolling tools are pushing the part away from its axis, causing drill or reamer eccentricity.

When drills follow each other, eccentricity will be least if each succeeding drill point has a slightly larger included angle. This lets the drill center itself properly instead of getting a bad start by having the point start first at the preceding drill's web section.

It has been my finding that more often hole concentricity is related to how freely a drill cuts, and how well it is centered in the holder.

"Feed" affects concentricity only when i. p. r. exceeds the rate which the tool can handle without crowding. "Part" is a troublemaking variable in concentricity when tolerances begin to approach the inherent eccentricity of the spindle-collet-workpiece package.

As mentioned at the start, the other three variables, Spindle Speed, Coolant and Human have little effect on concentricity, except to the extent that they may occasionally interact with one of the other four. We move to the fourth and final trouble, Surface Finish.

SURFACE FINISH

As shown in Table VIII 1, when the problem is unacceptable finish on the part, the variables rank in different order as potential trouble sources. In this case: Machine, Feed, Spindle Speed, Tooling, Coolant, Part and Human, respectively.

"Machine" is first because of the need for rigidity. Look and listen for signs and sounds of chatter. Do not change any other variables in an effort to improve finish until absolutely sure the machine has been snugged up as well as possible.

"Feed" has an effect mainly because a turned surface is for all practical purposes a thread whose pitch is equivalent to feed per revolution, and if that thread is to be blurred into a smooth-looking finish, its "pitch" must be very short.

"Spindle Speed," when increased, will help us obtain a smoother finish mainly by reducing the BUE. In general, smoother finish calls for running faster while taking light cuts at low i.p.r. feed rates. There's a limit to this, of course: At the point where tool edges start to burn, or wear rapidly, the advantages of higher s.f.m. are gone.

"Tooling" affects finish in a number of ways, through rigidity or the lack of it, through type of tool and manner of tool grinding, and through the use of adequately cleared yet well-supported cutting edges. The sequence is also important. When trouble develops, see what can be done to take the load off the finishing tool, and if possible, give it a position all its own. This is particularly worth considering when longitudinal turning or boring cuts are taken because side pressure during these operations almost certainly will cause poorer finish.

When a shaving tool creates the finish, strive for .0015 to .0025-inch of material on a side when r.m.s. is critical. More than that will lead to BUE, which in turn may cause tearing, or chatter.

In drilling and reaming, check widths of lands. In work hardening grades, leave as little margin as possible. For instance, on a 1/2 to one-inch reamer, no more than .010-inch uncleared margin is best if galling is to be avoided. We know that reducing chip thickness in effect reducing feed gives better finish. This can be accomplished on a reamer by putting a secondary chamfer of five to 15 degrees behind the standard chamfer of 38 to 45-degrees; i.e., 10 to 15 degrees for the work hardening steels, and under 10 degrees for other steels.

"Coolant" is a factor in avoiding rubbing, and in reducing BUE. Some oil men go into much detail on the mechanics of improving finish with cutting fluids. It is our finding that if the situation is sufficiently critical to require a change of coolant, an oil supplier should be called on for recommendations and perhaps in-shop assistance.

Finally, the "Human" element. Some men take great pride in finish; others couldn't care less. Look for the man who has a feel for properly ground and correctly set tools, and put him on the jobs where low r.m.s. must be achieved.

SUMMARY

As we close, let's recap the analyzing method described in this article. Step 1 is to find out, first hand, precisely what the problem is. Step 2 is to doublecheck all seven variables for obvious mistakes or misunderstandings and to make sure we have all the facts.

In both cases, findings should be written out for future reference. Step 3 is to check the variables in the order given under each type of problem in Table VIII-1. As we check, records should be kept.


Somewhere along the way, the problem will begin to come apart. As this occurs, the fault of the variable is corrected before proceeding.

Aim always for the true cause, rather than just trying to adjust what seems to be wrong.


As mentioned, when you're stumped, when you've tried everything, stop. Get away from the problem for a while so you can come back with a fresh outlook. Perhaps you've just worked on it so long you've begun to miss the same step every time.

An analysis of this sort can't be done in minutes, nor is it necessary in the easier cases. But when trouble is chronic, or when tolerances are so tight everything has to be right, a systematic approach is better, and in the long run cheaper, than running the risk of introducing new error to offset what's really wrong with the job.

FIG. VIII-3: Terms applying to twist drills




(Illustration courtesy of Metal Cutting Tool Institute, New York, N. Y.)



General point-thinning grind for steel.
Width is in relation to drill diameter.

Drill Diameter	Ratio
1/8	20:1
1/2	15:1
1	10:1



(Illustration courtesy of Metal Cutting Tool Institute, New York, N. Y.)





FIG. VIII-4: Terms applying to combined drills and countersinks



(Illustration courtesy of Metal Cutting Tool Institute, New York, N. Y.)

FIG. VIII-5: Checking the lip angle





FIG. VIII-6: Checking the point thinning grind for centrality














FIG. VIII-8: Checking lip relief with paper






- ① Mark where point of top paper (B) touches edge of bottom paper (A).
- ② Open paper, lay flat, and draw a diagonal line from A to B.
- ③ Read the lip relief angle as indicated.

DRILLS




PROBLEM	CAUSE	CORRECTION
<p>Drill chips on cutting lip edge</p> <p>Showing results of giving a drill too great lip-relief - the edges of the cutting lips have broken down because of insufficient support.</p>  <p>(Metal Cutting Tool Inst.)</p>	<p>Cutting lip weakened by excess lip relief angle</p> <p>Feed too heavy</p> <p>Unequal grind of lip width or web (drill point)</p> <p>Drill too far out of holder causing vibration</p> <p>Rake angle too small</p>	<p>Reduce lip relief angle</p> <p>Reduce feed</p> <p>Regrind</p> <p>Reset drill further back in holder</p> <p>Increase rake by grinding or use a faster helix drill</p>
<p>Drill chips on outer corners of cutting lips at margin (A)</p>  <p>(Metal Cutting Tool Inst.)</p>	<p>Spindle speed (r. p. m.) too high</p> <p>Insufficient rigidity</p>	<p>Reduce speed</p> <p>Snug up drill, holder, machine, etc.</p>
<p>Drill breaks</p> <p>CUTTING LIP SURFACE OF POINT</p>  <p>A dull point without any lip clearance. Note that corners of cutting lip A and of head B are in the same plane.</p> <p>(Cleveland Twist Drill Co.)</p> <p>(continued)</p>	<p>Lip relief angle too small</p> <p>Dull drill</p> <p>Spindle speed (r. p. m.) low in proportion to feed</p> <p>Drill seizing</p>	<p>Increase lip relief angle</p> <p>Regrind</p> <p>Increase speed or decrease feed</p> <p>When using several drills to attain hole depth, each succeeding drill should be .001/.002" smaller in diameter</p>

PROBLEM	CAUSE	CORRECTION
<p>Drill breaks (contd.)</p> 	<p>Chips clog flutes</p>	<p>Increase feed; decrease rake angle; widen flute by grinding; grind chip breaker on lip; use chip breaker drill; change point angle; use oil hole drill; increase coolant pressure; change position of coolant line lines</p>
<p>Two types of chip breakers (Metal Cutting Tool Institute)</p>	<p>Side pressure caused by another tool working in conjunction with drill</p>	<p>Change location or sequence of this tool; add a support to work</p>
	<p>Drill plunging into work</p>	<p>Broken or loose brake spring; cam rise too short; check, reset low speed dog or index dog</p>
<p>Incorrect Point. Lips of unequal length but at equal angles</p>	<p>Point grind not equal causing excess load on one lip or drill to walk off center</p>	<p>Regrind</p>
<p>(Metal Cutting Tool Inst.)</p>	<p>Drill protruding too far out of holder</p>	<p>Reset drill further back in holder</p>
	<p>Spindle loose</p>	<p>Repair or adjust spindle</p>
<p>Angles and lengths of cutting lips must be equal</p>	<p>(Illustration courtesy of Cleveland Twist Drill Company)</p>	
<p>Drill splits up center</p>	<p>Chisel edge or web too wide</p>	<p>Reduce thickness</p>
	<p>Feed too heavy</p>	<p>Reduce feed</p>
<p>(Metal Cutting Tool Inst.)</p>	<p>Lip relief angle too small</p>	<p>Increase lip relief angle</p>

DRILLS (contd.)


PROBLEM	CAUSE	CORRECTION
<p>Extreme outer corners of drill wear rapidly</p>  <p>The indication of Too Great Speed. The outer corners of the drill have worn away rapidly because excessive speed has drawn the temper.</p> <p>(Metal Cutting Tool Institute)</p>	<p>Spindle speed (r. p. m.) too high</p> <p>Rake angle too great</p> <p>Insufficient coolant</p> <p>Drill burned when sharpened</p>	<p>Reduce speed</p> <p>Reduce rake or use slower helix drill</p> <p>Assist heat removal by adding an extra line on drill or on workpiece</p> <p>Regrind making sure to remove all burned portions</p>
<p>Drill fails to bite into work</p>  <p>Proper way to grind lip-clearance. The angle indicated is the angle at the circumference of the drill</p>  <p>Front of dull after drill has been cut back in use and repointed</p>	<p>Lip relief angle too small</p> <p>Work hardening of material or surface by previous tool/tools</p> <p>Drill dull</p> <p>Web or chisel edge too wide</p> <p>Feed per revolution too low</p> <p>End play in spindle</p> <p>(Illustrations courtesy of Cleveland Twist Drill Company)</p>	<p>Increase lip relief angle</p> <p>Regrind previous tool, check, reset dwell to a minimum</p> <p>Regrind</p> <p>Reduce web or chisel edge width</p> <p>Increase feed</p> <p>Check, adjust spindle</p>
<p>Drill has a tendency to pull ahead during cut</p>	<p>Rake or helix angle too high</p> <p>End play in spindle</p>	<p>Reduce rake by grinding flat along drill lip; use slower helix drill</p> <p>Check and tighten up spindle</p>

DRILLS (contd.)



PROBLEM	CAUSE	CORRECTION
<p>Drill requires heavy feeding pressure throughout cut</p>  <p>The section on the left was cut from a drill near the point while the section on the right was cut near the shank. The difference in the thickness of the web at these two points is shown by the length of the white lines between the two sections in the illustration.</p>	<p>Chisel edge or web too wide</p> <p>Included point angle too large</p> <p>Lip relief angle too small</p>	<p>Decrease width of chisel edge or web</p> <p>Use less included point angle</p> <p>Increase lip relief angle</p>
<p>Drill cuts tapered hole</p>  <p>Incorrect Point. Lips of unequal length but at equal angles</p>	<p>Misalignment of drill</p> <p>Bent drill</p> <p>Drilled hole diameter reduced by subsequent operation (usually cross slide)</p> <p>Lips not equal</p> <p>Web not central</p>	<p>Realign drill</p> <p>Replace drill</p> <p>Check and reset subsequent operation tools that are causing the problem</p> <p>Regrind</p> <p>Regrind</p>
<p>Drill cuts undersize</p> 	<p>Worn margin on drill</p> <p>Insufficient or improper coolant</p> <p>Drill O.D. small</p>	<p>Remove worn area or change drill</p> <p>Increase amount of coolant and use correct grade</p> <p>Replace drill; "mike" O.D.</p>

(Cleveland Twist Drill Co.)

DRILLS (contd.)

PROBLEM	CAUSE	CORRECTION
<p>Drill cuts oversize</p>  <p align="center"><small>Incorrect Point. Lips of unequal length and at unequal angles</small></p> <p>(Cleveland Twist Drill Co.)</p>	<p>Lips not equal</p> <p>Chisel edge not central</p> <p>Drill out of line</p> <p>Machine spindles loose</p> <p>Drill clamped on margin causing axial misalignment</p> <p>Dull or incorrectly set tool working in conjunction with drill causing side pressure</p> <p>Drill oversize</p>	<p>Regrind</p> <p>Regrind and check 90° from the lip</p> <p>Realign drill</p> <p>Adjust spindles</p> <p>Clamp on shank; use screw machine stub drills</p> <p>Check, regrind or reset problem tool - change sequence of operation</p> <p>Change to proper size; "mike" O.D.</p>
<p>Drill cutting eccentric to axis of part</p>	<p>Drill lips unequal</p> <p>Web or chisel edge not central</p> <p>Drill bent</p> <p>Drill not aligned properly</p> <p>Side pressure caused by another tool</p>	<p>Regrind</p> <p>Regrind</p> <p>Replace</p> <p>Realign drill; if problem persists replace drill holder, collet or bushing and do not clamp on margin</p> <p>Relocate other tool or lower feeds and increase rake on other tool; add a support</p>

(continued)

PROBLEM	CAUSE	CORRECTION
<p>Drill cutting eccentric to axis of part (contd.)</p> 	<p>Spindle loose or bearings worn</p> <p>Drill's included point angle is smaller than previous drill or counter-sink</p>	<p>Tighten up spindle if possible</p> <p>Regrind drill making sure its included point angle is at least 2° more than the previous drill</p>
<p>Rough finish on hole</p>	<p>Drill is dull on cutting lips or margin</p> <p>Incorrect or insufficient coolant</p> <p>Welding on margin</p> <p>Drill not in alignment, causing rubbing on margin</p> <p>Chips clogging flutes</p>	<p>Regrind and remove all worn areas or replace</p> <p>Use proper coolant in copious amounts; use oil hole drill</p> <p>Reduce width of margin</p> <p>Realign drill; replace bushing; check holder alignment with spindle</p> <p>Use chip breaker grind; use oil hole drill; increase feed to obtain better chip shape</p>
 <p>(Cleveland Twist Drill Co.)</p>	<p>Incorrect grind</p> <p>Drill margin dragging along a previously cut hole of same diameter</p>	<p>Regrind and try a small 10° angle .010 / .020" wide on the outside corners at the margin of the drill</p> <p>When using several drills to attain hole depth, each succeeding drill should be about .001 / .002" smaller in diameter.</p>

NOTE: Check with drill manufacturers' recommendations and handbooks.

FIG. VIII-9: Terms applying to reamers





FIG. VIII-10: Stub screw machine reamer with straight shank and cross pin hole for drive floating holders



(Illustrations courtesy of Metal Cutting Tool Institute, New York, N. Y.)

FIG. VIII-11: Two methods of grinding the chamfer on a reamer for producing finish




FIG. VIII-11a: Types of reamers

Straight flute, right hand cut

Rose, straight flute, right hand cut

Left hand helical flute, right hand cut

Right hand helical flute, right hand cut

Taper pipe, spiral flute



Shell Reamers - High Speed

Straight flute



Helical flute

Arbors for Shell Reamers




Straight shank

Taper shank



(Illustrations courtesy of The Cleveland Twist Drill Co., Cleveland, Ohio)

REAMERS


PROBLEM	CAUSE	CORRECTION
Chipping of cutting edge	Insufficient rigidity (vibration)	Use less float
	Feed per revolution heavy	Reduce feed
Chatter	Spindle speed too high	Reduce spindle speed
	Reamer extended too far out of holder	Use shorter reamer or move reamer back in holder to reduce overhang
	Poor start because of insufficient or no chamfer	Chamfer front of hole to "lead" reamer
	Vibration	Too much float in holder: adjust or change holder
	Straight fluted reamer being used	Change to a spiral type: preferably right-hand cut - left-hand spiral or left-hand cut - right-hand spiral
	Drilled hole too close to reamer size	Use smaller drill
	Excessive chamfer relief	Reduce chamfer relief
	Removing too much material in proportion to feed	Use larger drill or slower feed
	Unequal grind of chamfer	Regrind to correct
	Margin too wide	Reduce width of margin to .005/.015"



REAMERS (contd.)


PROBLEM	CAUSE	CORRECTION
<p>Hole not round</p>	<p>Straight fluted reamer being used and cutting a hole smaller than the reamer diameter</p>	<p>Change to a spiral fluted reamer or a reamer that has diametrically unequal cutting edges</p>
<p>Bell mouth holes</p> 	<p>Incorrect alignment</p> <p>Reamer hitting bottom of hole</p> <p>Poor start</p> <p>Drilled hole too small causing excess removal of material</p> <p>Badly drilled hole</p> <p>Reamer chamfer ground unequally</p>	<p>Realign reamer; replace bushing; check holder alignment with spindle</p> <p>Move back into holder</p> <p>Check concentricity of starting chamfer or add a chamfer if there is none</p> <p>Increase drill or bore size</p> <p>Resharpen and/or realign drill</p> <p>Regrind to correct</p>
<p>Bell bottom holes</p> 	<p>Reamer striking bottom</p> <p>Misalignment of reamer or holder</p> <p>Drill cutting large at bottom of hole</p> <p>Chips fouling at bottom of hole</p>	<p>Move back into holder</p> <p>Realign reamer</p> <p>Regrind and reset drill</p> <p>Use oil hole reamer; change grind; increase drill size to cut down on chips; use spiral reamer</p>

REAMERS (contd.)

PROBLEM	CAUSE	CORRECTION
<p>Tapered hole</p>	<p>Reamer out of alignment</p> <p>Hole squeezed by subsequent operation</p> <p>Reamer worn</p>	<p>Adjust holder to realign reamer; check for bent reamer or holder</p> <p>Check subsequent operation</p> <p>Replace reamer or remove worn portion and re-grind chamfer</p>
<p>Rough hole</p> 	<p>Removing too much material</p> <p>Too much or not enough float in holder</p> <p>Welding of material on margin</p> <p>Built-up edge on cutting chamfer</p> <p>Improper coolants</p> <p>Not enough coolant</p> <p>Chips packing in flute</p> <p>Built-up edge along flute side of margin</p> <p>Reamer bent or out of alignment</p> <p>Burrs or nicks on reamer</p>	<p>Increase drill or bore size</p> <p>Readjust float</p> <p>Reduce width of margin</p> <p>Increase angle of chamfer; increase rake</p> <p>Use proper coolant for material from a finish standpoint</p> <p>Add an extra coolant line; use an oil hole reamer</p> <p>Feed too light; drill size too small; not enough coolant; use oil hole reamer</p> <p>Realign reamer; increase radial rake</p> <p>Replace or realign</p> <p>Remove nicks or replace reamer</p>

BORING TOOL DATA


FIG. VIII-12



BORING TOOLS


PROBLEM	CAUSE	CORRECTION
Tool breaks	Excessive clearance	Reduce clearance of primary angle
	Feed per revolution high	Reduce feed or increase speed if possible
Tool wears	Speed too high	Reduce speed
	Inadequate coolant	Use increased heat removing coolant; adjust volume of flow and alignment of coolant line
Tool chips	Vibration	Snug up machine; choke up tool holder
	Excessive clearance	Reduce clearance of primary angle
	Tool material too brittle	Change to tougher tool material
Tapered hole	Heavy feed	Reduce feed
	Tool dull	Resharpen
	Machine misalignment	Check spindle and boring bar slide alignment
Hole size varies	Worn tool	Sharpen
	Boring bar overhangs farther than necessary	Reduce overhang
	Machine not completely indexing	Repair indexing and locking mechanism

BORING TOOLS (contd.)


PROBLEM	CAUSE	CORRECTION
<p>Rough finish</p> 	Heavy feed	Reduce feed
	Tool dull	Resharpen
	Speed too low relative to tool cutting angles causing a larger built-up edge	Increase speed: increase tool top rake; resharpen smoother
	Improper or inadequate coolant	Use coolant that keeps built-up edge low and provides lubricity
	Drag out mark	Reduce primary clearance angle; reduce feed; rotate tool and holder into different position
	Tool above or below center	Recenter tool

FORM TOOL DATA


FIG. VIII-13




DOVETAIL
FORM TOOL






CIRCULAR
FORM TOOL





FLAT
FORM TOOL





FORMING TOOLS

PROBLEM	CAUSE	CORRECTION
<p>Tool breaking</p>	<p>Diving into cut</p> <p>Collets loose (bar slipping)</p> <p>Chips between tool and holder</p> <p>Tool dull</p>	<p>Increase throw</p> <p>Check and reset collets to proper tension</p> <p>Clean this surface before installing tool</p> <p>Resharpen</p>
<p>Tool chips</p> <p>Rough grind marks</p> <p>Chatter grind marks</p>  <p>Too much heat from grinding</p>	<p>Lack of rigidity</p> <p>Tool heated too much when sharpening, causing microcracks</p> <p>Tool not ground smooth</p>	<p>Add more or better support; reduce speed; check and tighten collets</p> <p>With high speed tools, keep cool with coolant when grinding; with cast alloy and carbide use less feed and clean grinding wheel</p> <p>Resharpen with proper wheel to a smoother surface</p>
<p>Tool wears</p>  <p>Heavy cratering weakens edge</p> <p>Side view</p> 	<p>Flank wear, not enough clearance</p> <p>Side wear from rubbing</p> <p>Heavy cratering causing weakening of cutting edge</p>	<p>Increase clearance</p> <p>Increase clearance (2° plus is good); change to a positive side cutting angle on tool; add a corner break on tool</p> <p>Increase back rake; grind rake surface smoother; use better coolant; change to better tool; decrease speed</p>

PROBLEM	CAUSE	CORRECTION
Tool does not hold size  <p data-bbox="225 722 540 810">Relationship of roller support and center line for proper support</p>	Improper tension on stops Tool dull Tool above or below center Part not properly supported Loose spindles Feed per revolution too heavy Machine not locating properly on index	Reset tension Resharpener Reset tool on center Reset support while part is revolving; variation in size of diameter being supported Check and tighten spindle bearings Reduce feed Check and correct condition
Taper on finished part  <p data-bbox="272 1268 521 1320">Tool ground out of square</p>	Tool not ground straight across rake surface Tool and holder not square with work Work springing away from tool	Resharpener and check with square Remove, clean and reset Add a support
Tool chatter (continued)	Tool below center Excess overhang Spindle vibration Excess back rake	Reset to center Reduce overhang Check and correct Decrease back rake






FORMING TOOLS (contd.)

PROBLEM	CAUSE	CORRECTION
<p>Tool chatter (contd.)</p> 	<p>Ratio of part formed length to smallest formed diameter (drive diameter) too great</p> <p>Feed too low</p> <p>Collet loose</p> <p>Nicks or burrs on tool holders</p>	<p>Add a support</p> <p>Increase feed</p> <p>Check and reset collet tension</p> <p>Check and correct</p>
<p>Rough finish</p> 	<p>Built-up edge too high</p> <p>Tool not on center</p> <p>Feed per revolution too high</p> <p>Dull tool</p> <p>Cutting area loaded with chips keeping coolant away from cutting edge</p> <p>Tool burned when manufactured or when sharpened</p>	<p>Increase back rake; decrease feed; use active sulfur mineral oil coolant; grind back rake smoother; increase speed</p> <p>Reset to center</p> <p>Reduce feed</p> <p>Resharpen</p> <p>Relocate tool; add an extra high pressure oil line to blow away chips; grind chip breaker</p> <p>Regrind and check tool surfaces (See section on Tool Grinding)</p>

PROBLEM	CAUSE	CORRECTION
Part breaking while forming	Job set too far out from collet	Reset closer
	Insufficient cam rise	Increase cam rise
	Excessive feed	Reduce feed
	Dull tool	Resharpen
	Tool above center	Reset tool to center
	Inadequate support	Add a support
	Loose slide	Check and adjust slide




CUT - OFF TOOL DATA

FIG. VIII-15





Side clearance - $2^{\circ}/4^{\circ}$
Front clearance - 8°

CUT - OFF TOOLS

PROBLEM	CAUSE	CORRECTION
<p>Cut-off breaks</p> 	<p>Heavy feed</p> <p>Too much overhang</p> <p>Out of alignment with prior cut</p> <p>Tool dull causing binding</p> <p>Slide loose causing uneven cutting and diving</p> <p>Insufficient cam rise</p>	<p>Reduce feed</p> <p>Reduce by moving tool back into holder</p> <p>Realign</p> <p>Resharpen</p> <p>Tighten slide and check slide rollers and pins</p> <p>Increase cam rise</p>
<p>Cut-off chips</p> 	<p>Lack of rigidity</p> <p>Not enough cam travel or rise</p> <p>Too large point angle</p> <p>Tool not on center</p>	<p>Check and tighten spindle, slide and tool holder</p> <p>Increase rise</p> <p>Decrease point angle</p> <p>Check and reset</p>
<p>Cut-off wears</p> 	<p>Spindle speed high</p> <p>Cut-off too narrow for depth of cut</p> <p>Lack of clearance on tool sides</p> <p>Inadequate amount of coolant causing tool burning</p>	<p>Reduce speed</p> <p>Use wider tool</p> <p>Check, regrind side clearance and make sure cut-off tool is straight in holder</p> <p>Relocate coolant line</p>

CUT - OFF TOOLS (contd.)

PROBLEM	CAUSE	CORRECTION
Variations in part length	Loose tool slide	Check and tighten
	Cut-off too thin	Use wider, sturdier tool
	Piece pushing back during previous operation	Check collet tension; tools may be dull
	End play in spindle	Check and reset end play
	Dull cut-off tool	Resharpen
	Excessive feed	Reduce feed
	Point angle too large	Reduce angle
	Chatter	Tool below center
	Not enough or too much clearance	Regrind to proper tool geometry
	Too much overhang	Reduce by moving tool back into holder
	Tool loose	Tighten holder
	Bad spindles or end play	Check and correct condition

CUT - OFF TOOLS (contd.)

PROBLEM	CAUSE	CORRECTION
Rough finish	Lack of coolant	Relocate and increase coolant
	Dull tool	Resharpen
	Tool rubbing on side	Increase side clearance: remove foreign matter from between tool and holder, which causes loss of side clearance
	Chips loading in cutting area	Grind chip breaker
	Tool not on center	Reset to center
	Not enough back rake	Increase back rake by changing tool holder or grinding in more rake on tool ($5^{\circ}/10^{\circ}$ is generally used)
	Excessive feed	Decrease feed
Spindle speed (rpm) low	Increase rpm	

- (1) Special cut-off tool for tubing (fish-tail)
- (2) V-type
- (3) Radial hook
- (4) Radius type
- (5) Chip groove
- (6) Straight hook

KNEE TURNING DATA

FIG. VIII-16







FIG. VIII-17: Three general-use chipbreakers



KNEE TURNING

PROBLEM	CAUSE	CORRECTION						
<p>Tool breaks</p>	<p>Lack of rigidity</p> <p>Burned tool causing cracks</p>	<p>Check spindles, tool holder and reduce overhang of tool; add support</p> <p>Regrind or change tool bit</p>						
<p>Tool wears</p> 	<p>Excess speed causing burning of edge</p> <p>Not enough relief</p> <p>Tool not on center</p> <p>Large built-up edge</p>	<p>Reduce speed</p> <p>Increase relief</p> <p>Reset tool bit</p> <p>Use active sulfur coolant; increase rake; grind smoother; reduce feed</p>						
<p>Tool chips</p>	<p>Excess relief</p> <p>Tool too hard or brittle</p>	<p>Reduce relief</p> <p>Change to a tougher tool steel or carbide</p>						
<p>Rough finish</p>  <p style="text-align: center;">SAE 1020 CHIP TEMPERATURE</p> <table style="margin-left: auto; margin-right: auto;"> <tr> <td style="text-align: center;">0° RAKE</td> <td style="text-align: center;">10° RAKE</td> <td style="text-align: center;">7° RAKE</td> </tr> <tr> <td style="text-align: center;">1150°F</td> <td style="text-align: center;">570°F</td> <td style="text-align: center;">690°F</td> </tr> </table>	0° RAKE	10° RAKE	7° RAKE	1150°F	570°F	690°F	<p>Improper or not enough coolant</p> <p>Tool corner sharp</p> <p>Feed per revolution high</p> <p>Vibration</p> <p>Not enough rake</p> <p>Dull tool</p>	<p>Use active sulfur coolant in large amounts at the cutting edge</p> <p>Grind a radius or a chamfer on tool corner</p> <p>Decrease feed</p> <p>Snug up machine and spindle; add support</p> <p>Increase rake</p> <p>Resharpen</p>
0° RAKE	10° RAKE	7° RAKE						
1150°F	570°F	690°F						


(R-O Mfg. Co.)

BOX TURNING DATA

(Box Mill, Box Tool)


This tool holder may utilize rollers or "V" rests.

FIG. VIII 18





Ⓛ (Land) = 1 to 1-1/2 times feed per revolution.

BOX TURNING TOOLS


PROBLEM	CAUSE	CORRECTION
Tool breaks	Rollers or V-rest not set right	Reset to proper pressure
	Tool jamming in	Check and tighten brake; check cam travel or rise
	Tool burned when sharpening	Resharpen
	Cast alloy or carbide tool cooled in water when sharpened, causing cracks	Regrind to remove cracks or replace tool
	Feed too heavy	Reduce feed
Tool wears 	Excess speed	Reduce speed
	Tool material not abrasion resistant or hard enough	Check into tool material and change
	Tool not on center	Recenter tool
	Large built-up edge	Increase rake; decrease width of land along cutting edge to equal approximately the feed per revolution; change coolant
Flaking on surface	Roller or V pressure too high	Reset pressure less
	Tool bit above center	Reset tool lower

BOX TURNING TOOLS (contd.)


PROBLEM	CAUSE	CORRECTION
<p>Spiral on surface</p> 	<p>Roller or V pressure uneven</p> <p>Tool not on center</p> <p>Tool chip breaker not large enough</p> <p>Land too wide along cutting edge and at point</p> <p>Large built-up edge</p>	<p>Adjust rolls or V blocks</p> <p>Recenter tool bit</p> <p>Increase width of V type chip breaker (curler) and possibly increase rake</p> <p>Reduce to proper width</p> <p>Change to proper coolant for finish; reduce land width; decrease feed</p>
<p>General rough finish</p>	<p>Rolls not round (hole or O.D.)</p> <p>Feed too high</p> <p>Improper or not enough coolant</p> <p>Chips packing</p>	<p>Check and replace</p> <p>Reduce feed</p> <p>Change coolant; increase flow; change coolant direction; add another line</p> <p>Use larger holder to help clear chips; change chip breaker; change or add an oil line</p>
<p>Tapered surface</p> 	<p>Excessive roll pressure</p> <p>Rolls not round</p> <p>Tool high on center</p>	<p>Reset and reduce pressure</p> <p>Replace</p> <p>Lower tool to center</p>

SHAVING TOOL DATA


FIG. VIII-19




SHAVE TOOLS

PROBLEM	CAUSE	CORRECTION
<p>Tool wears excessively</p>	<p>Spindle speed high</p> <p>Tool set ahead or behind roller</p> <p>Tool going past center</p> <p>Tool material not correct</p> <p>Feed too heavy</p>	<p>Reduce spindle speed</p> <p>Reset to center line of roller</p> <p>Reset throw of tool</p> <p>Select tool material for abrasion resistance qualities</p> <p>Reduce feed per revolution</p>
<p>Tool chips on edge</p>	<p>Spring in holder weak or broken</p> <p>Built-up edge high</p>	<p>Replace</p> <p>Reduce feed; increase rake; use proper coolant; grind rake smoother or hone</p>
<p>Chatter</p>  <p>(continued)</p>	<p>Feed per revolution heavy</p> <p>Spindle speed high</p> <p>Roller and/or pin worn</p> <p>Shave holder worn</p> <p>Not enough rake</p>	<p>Reduce feed</p> <p>Reduce spindle speed</p> <p>Check and replace</p> <p>Check and replace or shim to snug up</p> <p>Increase rake possibly up to 20°; rake generally used is 30°/50°</p>

SHAVE TOOLS (contd.)

PROBLEM	CAUSE	CORRECTION
<p>Chatter (contd.)</p> 	<p>Too much material being removed</p> <p>Vibration</p> <p>Machine spindles worn - index not locking</p>	<p>Check and reset to a minimum; i.e., .0015 to .003 on a side</p> <p>Grind 2° shear angle on front of tool; set tool ahead of roller center line; decrease amount of lift of tool holder; attach a large piece of lead to shave tool holder; use heavier springs in holder</p> <p>Check and correct condition</p>
<p>Variation of part diameter</p>	<p>Built-up edge heavy</p> <p>Tool dull</p> <p>Tool edge ahead or behind center line</p> <p>Blank tapered</p> <p>Roller or pin has flats or is not round</p> <p>Too much material being removed by shave tool</p>	<p>Increase rake; decrease feed; change coolant; hone rake</p> <p>Resharpener</p> <p>Reset tool on center</p> <p>Straighten out form tool</p> <p>Replace roller / pin</p> <p>Reduce amount of material to be removed on a side: .0015/.003 is best to hold size and roundness</p>

SHAVE TOOLS (contd.)


PROBLEM	CAUSE	CORRECTION	
Workpiece breakage	Tool diving into piece	Increase cam rise and or reposition tool to center line of part	
	Piece set too far from collet	Reset job closer to collet	
	Tool removing too much material	Reduce blank size diameter	
	Tool ahead or behind roller center line causing excess pressure	Reset tool to roller center line	
Shaved diameter tapered	Tool not square with roller	Reset tool	
	Tool not ground square	Resharpen	
	Defective holder	Check and replace	
	Holder not square	Adjust	
	Rough finish	Dull tool	Resharpen
		Tool form finish is rough	Remake tool or replace
		Blank diameter too large	Reduce blank diameter
		Improper or inadequate coolant	Use proper coolant in copious amounts; for steel use active sulfur oil
(continued)			

SHAVE TOOLS (contd.)


PROBLEM	CAUSE	CORRECTION
Rough finish (contd.)	Blank surface rough	Resharpen blank form tool and increase rake on this tool (use Dykem on blank prior to shave cut; if traces of color are visible after shave cut, blank is too rough)
	Tool not set on roller center line	Reset tool
	Built-up edge heavy	Increase rake angle; decrease feed; change coolant; increase speed; grind rake or hone extra smooth

SKIVING TOOL DATA

FIG. VIII-20




SKIVING TOOLS



PROBLEM	CAUSE	CORRECTION
<p>Tool edge chipping</p>  <p style="text-align: center;">Skiving tool</p>	<p>Rake angle too high</p> <p>Built-up edge</p> <p>Vibration</p>	<p>Reduce rake angle; recommended starting rake angles are: Brass 17°, Aluminum 20°, Steel 25°</p> <p>Grind better surface finish on cutting edge; use active sulfur coolant</p> <p>Check tool holder; add a support</p>
("American Machinist")		
<p>Tool wears excessively</p>	<p>Spindle speed too high for material</p> <p>Feed per revolution too high</p> <p>Tool burned when made or when sharpened</p>	<p>Reduce spindle speed</p> <p>Reduce feed per revolution</p> <p>Check surface hardness of tool form and rake</p>
<p>Variation in part diameter</p>	<p>Tool dull</p> <p>Lack of rigidity</p> <p>Excessive clearance</p> <p>Too much overhang of tool</p>	<p>Resharpener</p> <p>Use a support</p> <p>Check and reduce clearance; recommended clearance angle is 12°</p> <p>Reduce overhang</p>
<p>(continued)</p>		

SKIVING TOOLS (contd.)

PROBLEM	CAUSE	CORRECTION
Variation in part diameter (contd.)	Excessive feed	Reduce feed per revolution
	Shear angle too small	Increase shear angle
	Tool not perpendicular to axis of part causing side rubbing	Check and reset tool
	Insufficient rake angle	Increase rake angle
Work piece breaking	Excessive feed	Reduce feed
	Lack of support	Use support
	Shear angle not large enough	Increase shear angle
	Tool or holder loose	Check and tighten
	Spindle loose	Check and repair
	Tool and part too far out of collet	Reset closer to collet
	Tool plunging into work	Increase cam rise or travel
Chatter	No support or improper support	Use best support possible
	Not enough rake	Increase rake
	Too much overhang of tool	Reduce overhang
	Lack of rigidity	Check and snug up spindle, slides and tool holder

SKIVING TOOLS (contd.)



PROBLEM	CAUSE	CORRECTION
<p>Rough finish</p> 	Not enough rake	Increase rake angle
	Improper coolant	Correct coolant: for steel use an active sulfur oil.
	Tool surface finish poor	Remake tool with improved surface finish
	Dull tool	Resharpen
	Spindle speed too low causing large built-up edge	Increase spindle speed
	Insufficient shear angle	Increase shear angle
	Insufficient coolant	Increase coolant volume not velocity



Illustrations from "Skiving on Automatics" - AMERICAN MACHINIST, February 1966, courtesy of the McGraw-Hill Publishing Company.
VIII-53

TAP DATA

FIG. VIII-21: Terms applying to Taps



Helical fluted hand tap



Taper pipe tap



Bottoming tap



Plug tap



Taper tap






Interrupted thread taper pipe tap





(Illustrations courtesy of the Metal Cutting Tool Institute, New York, N. Y.)




TAPS

PROBLEM	CAUSE	CORRECTION
<p>Tap breaking</p>  <p>Chip packing may be overcome by a shorter thread depth or a lower percentage of thread ("American Machinist")</p>  <p>(Greenfield Tap & Die)</p>  <p>(Bay State Tap and Die)</p> <p><i>BENT OR CROOKED HOLES are those whose axes are not straight, generally produced by tools "loading off". Threads will tend to follow the hole.</i></p>	<p>Tap hitting bottom</p> <p>Chips jam when tap is pulling out</p> <p>Lack of coolant</p> <p>Chamfer angle short</p> <p>Welding on tap surface</p> <p>Hole too small (thread percentage too high)</p> <p>Eccentric hole</p> <p>Dull tap</p> <p>Spindle speed too slow</p> <p>Misalignment</p>	<p>Increase drill depth or reduce depth of tapping</p> <p>Reduce tap land; change grind to change chip shape</p> <p>Use oil hole tap or add coolant lines</p> <p>Increase length of chamfer angle</p> <p>Reduce land; change coolant; reduce spindle speed</p> <p>Check and use larger drill or reamer to produce less thread percentage: 60% if print allows</p> <p>Correct drilling problem</p> <p>Resharpen</p> <p>Increase spindle speed</p> <p>Realign tap</p>
<p>Tap chipping</p> <p>(continued)</p>	<p>Hole chamfer not concentric or large enough</p> <p>Excessive rake, hook angle or chamfer angle relief</p>	<p>Reset and resharpen spotting drill</p> <p>Reground or replace tap</p>







TAPS (contd.)

PROBLEM	CAUSE	CORRECTION
<p>Tap chipping (contd.)</p>  <p>(R-O Mfg. Co.)</p>	<p>Tap not in line with spindle</p> <p>Tap being crowded into cut</p> <p>Unequal chamfer grind</p> <p>Spindle speed too slow</p>	<p>Realign tap</p> <p>Decrease cam rise, change or use slower cycle time to decrease feed on tap, reduce spring pressure</p> <p>Resharpen tap</p> <p>Increase spindle speed</p>
<p>Variation in pitch diameter</p>  <p>(Greenfield Tap & Die)</p>	<p>Tap crowding</p> <p>Dull tap</p> <p>Floating holder worn</p> <p>Hole diameter varies or out of round</p> <p>Excessive land on tap</p> <p>Not enough rake or hook angle</p> <p>Flutes not large enough, chips packing</p>	<p>Check cam rise</p> <p>Resharpen</p> <p>Replace</p> <p>Check and regrind drill, reamer or boring tool</p> <p>Regrind in flute to lessen lands; use land relief tap</p> <p>Increase rake or hook angle</p> <p>Grind flute or change tap</p>
<p>Tap "picking up"</p> <p>(continued)</p>	<p>Not enough rake or hook angle</p>	<p>Increase rake or hook angle</p>

TAPS (contd.)


PROBLEM	CAUSE	CORRECTION
Tap "picking up" (contd.)	Rake or hook not ground smooth	Regrind smoother and polish
	Land too wide	Grind in flute to reduce land; use land relief tap
(Bay State Tap and Die)	Insufficient or incorrect coolant	Change coolant and increase amount
	Tap burned when sharpened	Regrind or replace
	Dull tap	Resharpen or replace; tap may have been used too long without sharpening
	Chamfer relief insufficient	Increase chamfer relief
Tap cutting oversize	Misalignment	Realign tap
	Spindle speed too slow	Increase spindle speed
("American Machinist")	Improperly ground tap	Regrind or replace
	"H" size of tap incorrect	Use lower size class of tap
	Improper coolant	Change coolant
	Blank hole not to size or out of round	Check drill and reset or regrind
	Starting chamfer in hole not large enough or not concentric	Increase hole chamfer size and reset spot drill
	Worn tap picking up on lands	Reduce speed; increase hook; realign tap; change coolant; grind longer chamfer
(R. O. Mig. Co.)		

TAPS (contd.)

PROBLEM	CAUSE	CORRECTION
Rough threads	Incorrect or insufficient coolant	Change coolant to an anti-weld type and increase amount
	Dull tap or burned when sharpened	Resharpener or replace
	Spindle speed high or too low	Reduce speed if edge is burned or decrease speed if built-up edge is high
	Misalignment of tap	Realign tap
(Bay State Tap and Die Co.)	Chips packing in flutes	Increase size of flutes; polish flutes; use spiral tap; use oil hole tap
	Blank hole small (thread percentage high)	Increase drilled hole size; 60% thread if print allows
(Geometric Tool Co.)	Chamfer angle not long enough (chip thickness heavy)	Increase chamfer angle; 3 thread angle or more is most desirable
HANDLING AND STORAGE		
		
<p>Wooden trays or drawers with dividers to isolate each tap.</p>	<p>Protective tubes</p>	<p>The original packages, if available</p>
		
	<p>Plastic or similar protective coating.</p>	
(Bay State Tap and Die Co.)		

CHASER DATA

FIG. VIII-23: Insert chasers



H&G INSERT CHASER NOMENCLATURE




FIG. VIII-24: Die head chasers, blade type, tapped (R H shown)





FIG. VIII-25: Die head chasers, blade type, milled (R H shown)



(Fig. 23 courtesy of H & G Division of The Cleveland Twist Drill Co., Cleveland, O.)
 (Figs. 24 and 25 courtesy of The Metal Cutting Tool Institute, New York, N.Y.)

CHASER DATA

FIG. VIII-26: Tangent chasers




FIG. VIII-27: Die head chasers, tangent type (R H shown)




FIG. VIII-28: Circular chasers




FIG. VIII-29: Die head chasers; circular type (R H shown)




FIG. VIII-30: Tap chaser




FIG. VIII-31: Regular tap chasers, blade type (R H shown)










FIG. VIII-32: Projection tap chaser, blade type






(Illustrations courtesy of the Metal Cutting Tool Institute, New York, New York)

CHASERS

PROBLEM	CAUSE	CORRECTION
<p>Chaser breakage</p> <hr/> <p style="text-align: center;">CORRECTLY GROUND SET</p>  <p style="font-size: small;">Note that chamfer is slightly different on each chaser of set.</p>	<p>Chasers hit shoulders</p> <p>Blank out of round, over-size or not concentric</p> <p>Die head not aligned</p> <p>Dull or worn chasers</p>	<p>Reset die head opening mechanism</p> <p>Check blank and reset tools</p> <p>Realign holder</p> <p>Resharpen chasers before they are too dull</p>
<p style="text-align: center;">INCORRECTLY GROUND SET</p>  <p style="font-size: small;">Chaser B is correctly ground. Chaser C has been ground with too long a chamfer. Chaser D has too short a chamfer. Also Chaser A is too thin and not of the same thickness as the other three chasers of the set.</p>	<p>Die head sloppy</p> <p>Improper coolant causing large built-up edge to form</p> <p>Chamfer grind not equal on all chasers</p>	<p>Repair die head</p> <p>Change coolant to anti-weld type</p> <p>Regrind</p>
<p>Chaser wear excessive</p> <hr/> <p style="text-align: center;">DEPTH OF CHAMFER</p>  <p style="font-size: small;">The chamfer should start .005\" to .015\" below the root of the chaser teeth. All chasers of a set should be ground at uniform angle and depth so that each chaser will start cutting at the same time.</p>	<p>Spindle speed high</p> <p>Incorrect coolant</p> <p>Chamfers not ground equally</p> <p>Chamfer not long enough</p> <p>Not enough rake or hook</p> <p>Cam rise improper causing crowding or pulling of head</p> <p>Chaser burned when made or sharpened</p> <p>Die head out of line with spindle</p>	<p>Decrease spindle speed</p> <p>Change coolant</p> <p>Resharpen</p> <p>Increase length of chamfer</p> <p>Increase rake or hook</p> <p>Use proper cam rise</p> <p>Check and resharpen</p> <p>Realign die head</p>
<p>(Geometric Tool Co.)</p>		

PROBLEM	CAUSE	CORRECTION
<p>Variation in pitch</p>  <p>(Geometric Tool Co.)</p>	<p>Die head locking pin worn Die head springs weak or broken Variation in blank size Cam rise incorrect causing crowding or drag Spindle speed too high Dull chasers Chamfer relief inadequate</p>	<p>Replace locking pin Replace springs Check and reset tools cutting blank Check and change cam rise Decrease spindle speed Resharpen Regrind chamfer</p>
<p>Tapered threads</p>  <p>(Geometric Tool Co.)</p>	<p>Misalignment Chamfer unequal Worn die head locking pin Die head crowding on blank Loose die head parts or chips inside head Chasers or carriers sloppy in die head Dirt under chasers or in die head Chasers shave Machine loose Poor start of chasers on blank</p>	<p>Realign die head or spindle; check for bent shank on die head Resharpen Replace locking pin Check camming and change Check, clean, and retighten Replace die head or chasers; remove plates, check for burrs and dirt Clean out Remove sharp edge on chasers Correct machine conditions Increase chamfer; make sure it's not work hardened; check cam and starting spring</p>

CHASERS (contd.)

PROBLEM	CAUSE	CORRECTION
Lead error	Chasers shaving	Remove sharp chaser edge or burr; pull each chaser across a flat piece of lead with valve grinding compound on it. Remove dirt or chips on chaser holders - remove nicks or burrs from chasers, slot or holder
 <p>Chasers are twisted in respect to each other when lapping for lead.</p>	Die head pushing on blank Die head out of line Chamfers not equal	Check camming and change Realign head Resharpen
(Geometric Tool Co.)		
Rough threads	Spindle speed too high or low	Decrease if chasers are burned; increase if built-up edge is large
Attempting to remove too much material with chasers.	Blank too large	Decrease blank size
	Rake or hook incorrect	Increase rake or hook angle
(Geometric Tool Co.)	Incorrect coolant	Change to anti-weld type coolant
	Die head out of line with spindle	Realign die head or threading spindle
	Die head pushing or pulling	Correct camming to acquire that the die head follows properly
	Chamfers unequal	Resharpen
	Burr on chasers edge from grinding	Remove burrs carefully so that thread is not deformed
	Chasers dull	Resharpen
	Chasers nick shoulder	Adjust stop

KNURLING DATA

FIG. VIII- : Nomenclature
























FIG. VIII- : Types of knurls

 STRAIGHT	 L.H. DIAGONAL	 R.H. DIAGONAL	 R. & L.H. DIAGONAL	 FEMALE DIAMOND																																										
 Straight	 R.H. Diagonal	 L.H. Diagonal	 Male Diamond (Raised Points)	 Male Diamond (Raised Points)																																										
 Straight	 R.H. Diagonal	 L.H. Diagonal	 Male Diamond (Raised Points)	 Male Diamond (Raised Points)																																										
 Straight	<p>Approximate Increase of Blank Diameters with Standard Reed Circular Pitch Knurls on Soft Steels</p> <table border="1" style="margin: auto; border-collapse: collapse;"> <thead> <tr> <th rowspan="2">*Teeth per Inch</th> <th rowspan="2">Straight and Diagonal** Knurling</th> <th colspan="2">**Diamond Knurling</th> </tr> <tr> <th>Male- (Raised Points)</th> <th>Female (Depressed Points)</th> </tr> </thead> <tbody> <tr> <td>12</td> <td>.034</td> <td>.038</td> <td>..</td> </tr> <tr> <td>16</td> <td>.025</td> <td>..</td> <td>..</td> </tr> <tr> <td>20</td> <td>.020</td> <td>.023</td> <td>.014</td> </tr> <tr> <td>25</td> <td>.016</td> <td>.018</td> <td>.011</td> </tr> <tr> <td>30</td> <td>.013</td> <td>.015</td> <td>.009</td> </tr> <tr> <td>35</td> <td>.011</td> <td>..</td> <td>..</td> </tr> <tr> <td>40</td> <td>.009</td> <td>.010</td> <td>..</td> </tr> <tr> <td>50</td> <td>.009</td> <td>.010</td> <td>.007</td> </tr> <tr> <td>80</td> <td>.005</td> <td>.006</td> <td>..</td> </tr> </tbody> </table> <p>*Refers to normal teeth per inch on diagonal and diamond knurling. **With 30° helix angle.</p>				*Teeth per Inch	Straight and Diagonal** Knurling	**Diamond Knurling		Male- (Raised Points)	Female (Depressed Points)	12	.034	.038	..	16	.025	20	.020	.023	.014	25	.016	.018	.011	30	.013	.015	.009	35	.011	40	.009	.010	..	50	.009	.010	.007	80	.005	.006	..
*Teeth per Inch							Straight and Diagonal** Knurling	**Diamond Knurling																																						
					Male- (Raised Points)	Female (Depressed Points)																																								
12					.034	.038	..																																							
16					.025																																							
20	.020	.023	.014																																											
25	.016	.018	.011																																											
30	.013	.015	.009																																											
35	.011																																											
40	.009	.010	..																																											
50	.009	.010	.007																																											
80	.005	.006	..																																											
 Male Diamond (Raised Points)																																														
 R. or L.H. Diagonal (R.H. Diagonal Shown)																																														

(Illustrations courtesy of the Reed Rolled Thread Die Co., Holden, Mass.)

KNURLING


PROBLEM	CAUSE	CORRECTION
Knurl wearing	Spindle speed too high Knurl feeding on too slowly (too many revolutions) Incorrect coolant	Reduce speed Increase feed per revolution Change coolant
Knurl not tracking $\frac{\text{Teeth on knurled part}}{\text{Blank diameter}} = \frac{\text{Diametrical pitch}}{\text{pitch}}$ Example:  $\frac{48}{.500} = 96$	Feed per revolution too low Pitch of knurl incorrect for blank Knurl sticking in holder	Increase feed per revolution Check and change knurl or blank size Check and free up
Oversize knurl	Blank large Excessive pressure on knurls	Decrease blank size Reduce pressure
Undersize knurl	Blank diameter small Insufficient pressure on knurls	Increase blank size Increase pressure
Straight knurl spiraling 	Knurl set at an angle to axis	Reset knurls

KNURLING (contd.)


PROBLEM	CAUSE	CORRECTION
Knurl flaking	Too many revolutions used to knurl	Increase feed per revolution
	Blank too large (over knurling)	Decrease blank size
	Knurls not lined up with axis of part	Realign
Knurl variation in size or form	Variation in blank size	Sharpen form tool; check tension stops for too much or too little pressure
	Worn or broken knurl/knurls	Replace knurls
	Tapered blank	Reset form tool
	Uneven adjustment of twin knurls	Reset (Stop knurl at center of part. Allow several rotations <u>without feed</u> to "clear" knurl. BOTH knurls should be tight.)
	Knurl not on center	Reset

THREAD ROLLING DATA

FIG. VIII- : Terms applied to Unified and American External Screw Threads



Thread Form





*On single threads, the lead and pitch are the same. On multiple threads (double, triple, quadruple, quintuple, sextuple) the lead is an integral multiple of the pitch.

Screw Thread

(Illustrations courtesy of the Reed Rolled Thread Die Co., Holden, Mass.)

THREAD ROLLING

TROUBLE	CAUSE	
	TWO-ROLL GEARED ATTACHMENT	SINGLE ROLL HOLDER
Slivers or flakes on threads	Rolls not in match Center line of rolls not parallel with center line of work Loose or worn cross slide or adapter Overfilling rolls Material not adaptable to cold working Rough finish on blank Seamy stock Feed rate too slow, causing rolls to slip on work Incorrect roll diameter	Center line of roll not parallel with center line of work Loose or worn cross slide or holder Overfilling roll Material not adaptable to cold working Rough finish on blank Seamy stock Feed rate too slow, causing rolls to slip on work Incorrect roll diameter
 		
Drunken threads	Rolls not in match Center line of rolls not parallel with center line of work Inaccurate rolls Work bending during rolling	Center line of roll not parallel with center line of work Inaccurate roll Work bending during rolling
Thread with expanded lead	Expanded lead in rolls Material extruding on short length of blank	Expanded lead in roll Material extruding on short length of blank
Thread with contracted lead	Contracted lead in rolls	Contracted lead in roll

THREAD ROLLING (contd.)

TROUBLE	CAUSE	
	TWO-ROLL GEARED ATTACHMENT	SINGLE ROLL HOLDER
<u>Offsize threads</u>		
Pitch Diameter and Major Diameter both oversize	Oversize blanks	Oversize blanks
Pitch Diameter oversize, Major Diameter correct size	Oversize blanks; if finished thread is full, thread on roll is too shallow	Oversize blanks; if finished thread is full, thread on roll is too shallow
Pitch Diameter oversize, Major Diameter undersize	Insufficient squeeze on rolls; if finished thread is full, thread on roll is too shallow	Insufficient penetration of roll in work; if finished thread is full, thread on roll is too shallow
Pitch Diameter correct size, Major Diameter oversize	Blank too large; thread on roll deeper than necessary	Blank too large; thread on roll deeper than necessary
Pitch Diameter correct size, Major Diameter undersize	Blank too small; if finished thread is full, thread on roll is too shallow	Blank too small; if finished thread is full, thread on roll is too shallow
Pitch Diameter undersize, Major Diameter oversize	Too much squeeze; thread on roll deeper than necessary	Too much penetration of roll in work; thread on roll deeper than necessary
Pitch Diameter undersize, Major Diameter correct size	Blank too small; thread on roll deeper than necessary	Blank too small; thread on roll deeper than necessary
Pitch Diameter and Major Diameter both undersize	Blank too small	Blank too small

THREAD ROLLING (contd.)

TROUBLE	CAUSE	
	TWO-ROLL GEARED ATTACHMENT	SINGLE ROLL HOLDER
<u>Tapered threads</u>		
Pitch Diameter straight Major Diameter tapered and not filled out on small end	Tapered blank	
Pitch Diameter and Major Diameter both tapered same way	Tapered blank and rolls set up with taper to match	Tapered blank and roll set up with taper to match
Pitch Diameter and Major Diameter tapered in op- posite directions and thread not filled out on end with small Major Di- ameter	Rolls not squeezed tight enough on edge with large Pitch Diameter and small Major Di- ameter, or work bending during rolling	Work bending during roll- ing
Out-of-round thread	Out-of-round blank Center line of rolls not parallel with center line of work Feed rate too high Insufficient work revolu- tions Material not ductile enough for cold- working Not rolling to center line of work	Out-of-round blank Center line of roll not parallel with center line of work Feed rate too high Insufficient work revolu- tions Material not ductile enough for cold- working
Split thread-axially	Seamy stock Mark from shave tool or hollow mill	Seamy stock Mark from shave tool or hollow mill

THREAD ROLLING (contd.)

TROUBLE	CAUSE	
Poor thread form	<p>TWO - ROLL GEARED ATTACHMENT</p>	<p>SINGLE ROLL HOLDER</p>
Poor finish on threads	<p>Overfilling rolls Rolls not in match Material accumulated in threads on roll Material not ductile enough for cold-working Chips from other operations between rolls and work Correspondingly poor finish on rolls Rolls that are worn or broken</p>	<p>Overfilling roll Material accumulated in threads on roll Material not ductile enough for cold-working Chips from other operations between rolls and work Correspondingly poor finish on roll Roll that is worn out or broken</p>
	Thread filled out in center, but not towards ends, or vice versa	<p>Roll with varying diameter from end to end Blank with varying diameter from end to end Center line of rolls not parallel with center line of work</p>

THREAD ROLLING (contd.)

TROUBLE	CAUSE	
	TWO - ROLL GEARED ATTACHMENT	SINGLE ROLL HOLDER
* Crests not filled out	Blank too small Thread on roll too deep	Blank too small Thread on roll too deep
* Many users do not consider this a serious objection; and by allowing their threads to pass with crests not filled out, overloading of rolls is avoided and roll life is prolonged.		
Scuffed crests	Attachment not retracting fast enough Rolls and gear train binding Rolling beyond center line of work Material accumulated in threads on rolls	Holder not retracting fast enough Roll binding Material accumulated in threads on rolls
Hollow work, hole closes in	Machine hole after rolling Needs supporting mandrel Feed rate too high, causing too rapid penetration	Machine hole after rolling Needs supporting mandrel Feed rate too high, causing too rapid penetration
Hollow work, hole enlarged	Machine hole after rolling Supporting mandrel too tight Blank too large on Major Diameter Feed rate too high causing too rapid penetration	Machine hole after rolling Supporting mandrel too tight Blank too large on Major Diameter Feed rate too high causing too rapid penetration

THREAD ROLLING (contd.)

TROUBLE	CAUSE	
	TWO - ROLL GEARED ATTACHMENT	SINGLE ROLL HOLDER
Hollow work, out of round	Machine hole after rolling Feed rate too high causing too rapid penetration Too few work revolutions	Machine hole after rolling Feed rate too high causing too rapid penetration Too few work revolutions
Hollow work, tapered threads due to uneven wall thickness or support from adjacent section	Machine hole after rolling Improper mandrel not giving support where needed Feed rate too high causing too rapid penetration Taper of rolls not great enough to compensate for tendency of work to taper Too thin wall thickness	Machine hole after rolling Improper mandrel not giving support where needed Feed rate too high causing too rapid penetration Taper of roll not great enough to compensate for tendency of work to taper Too thin wall thickness

The foregoing information on Thread Rolling has been reproduced from the Reed Rolled Thread Die Company handbook on thread and form rolling



AUTOMATIC HOUSE, Discovery Way, Leofric Business Park, Binley, Coventry CV3 2TD
Telephone +44 (0) 24 7654 7900, Facsimile +44 (0) 24 7654 7950, Web Site: www.wickman.co.uk

